



NOTE: Upgrading to this firmware will not erase any settings.

2.0.8p1

- Adds increased functionality for syslogging during troubleshooting.

2.0.8

SNMP additions:

- “Read Community String” and “Write Community String” have options for public and private now.

2.0.7

Bug Fixes:

- IP5000 now can move from a network using DHCP to an isolated static network when utilizing recordings in the phone.
- Resolves an issue with the connection to an Avaya Session Boarder Controller that requires an ACK repeatedly during RTP transmission.
- Resolves an issue with connections to a network that uses the Qualys Network Vulnerability service.

Please email ts@codeblue.com or call 800.205.7186, opt. 3 if you have any additional questions or concerns about this upgrade.